Work description report

Community Center project – Sainovac

I. Interior works:





The entire electricity installation is being replaced as the old one is very much damaged and burnt and can cause serious problems in the future if not replaced by the new wires





The conference hall is getting flat and ready for concreting. The ground level was a bi higher then normal so we had to dig and take one layer off.





The water installation is being prepared

II. Exterior works:



The dirt from the digging is being transported by the rented tractor from the site.





The balcony is being reinforced and concreted